

Attachment 4

**Honda's
October 3, 2003
Recall "Package" Documents**

October 3, 2003

NVS-214jry
PE03-039

Mr. Richard P. Boyd, Chief
MHTD Division
Office of Defects Investigation
U.S. DEPARTMENT OF TRANSPORTATION
National Highway Traffic Safety Administration
400 Seventh Street, S.W.
Washington, DC 20590

Dear Mr. Boyd:

Enclosed are materials prepared for the GL1800 frame weld recall.

- Recall service bulletin
- Frame weld inspection chart
- Recall dealer procedure manual
- Frame welding manual
- Welding template kit

Also enclosed is a letter to GL1800 owners whose frames are **not** affected by the recall.

If you have questions, please contact me.

Sincerely,

AMERICAN HONDA MOTOR CO., INC.



William R. Willen
Managing Counsel
Product Regulatory Office

Enclosures