




2002-2003 GL1800/A Frame Weld Safety Recall

Frame Weld Inspection Chart

Refer to Service Bulletin GL1800/A #14

IMPORTANT:


If you find any No Good welds, call your DSM or TechLine at (800) 421-1900 for further instructions.




2002-2003 GL1800/A Safety Recall:

No Good Welds


1 Concave Weld




2 Cold Weld



3 Under Cut Weld




4 Dirty Weld




Frame Weld Inspection Chart

5 Too Short Weld



6 Too Long Weld



Good Welds

